

**Title \*** Curry STO-81-1.36  
**Culvert/Bridge Number** STO-81-1.36  
**Geo Location** 39.728356729997714 -83.64113554358484  
**General Appraisal** 7 Good condition - some minor problems  
**Span Size**  
**Culvert Length**  
**Size of Culvert**  
**Type Culvert** RCP

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 6 Satisfactory Conduit waterway blockage is less than 10% of the cross-sectional area of the opening. Sediment buildup causing flow through 1 of 2 pipes.  
**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.  
**Guardrail**  
**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.  
**Comments** Culvert 50% full with silt  
**Owner** Rapp, Aaron  
**Completed DateTime** 01/28/2025 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage  
**Request Status** 5 - Closed