

Title * Markley UNI-105-1.10

Culvert/Bridge Number UNI-105-1.10

Geo Location 39.91230382772135 -83.53790938854219

General Appraisal 5 Fair condition - all primary structural elements are sound, but may have minor section loss

Span Size 5 feet

Culvert Length 20 feet

Size of Culvert 5x3 box

Type Culvert Concrete

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

Material 5 FAIR

Conduit Alignment 7 GOOD

Shape 7 GOOD

Seams and Joints 7 GOOD

Slab 6 Satisfactory Hairline map cracking combined with molted areas. Cracks less than 1/8 inch parallel to traffic with minor efflorescence or minor amounts of leakage.

Abutments 4 POOR

Headwalls 5 Fair Map cracking. Horizontal and diagonal cracks. Differential or rotational settlement. Barrel pulling away from headwall

End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.

Scour 3 Serious Major scour holes, 3 feet or deeper, at inlet or outlet undermining cutoff walls or headwalls. Footing is undermined.

Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.

Guardrail 7 Good Minor settlement or misalignment that affect the condition of the guardrail within 50 feet of the conduit. Limited to one or two guardrail posts.

Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Rapp, Aaron

Completed DateTime 01/29/2025 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage

Request Status 5 - Closed