

Title * Van Wagener OAK-84-3.35
Culvert/Bridge Number OAK-84-3.35
Geo Location 39.8345653011466 -83.38625997304918
General Appraisal 3 Serious condition - loss of section, deterioration, or spalling have seriously affected primary structural components
Span Size 36 inch
Culvert Length 40 feet
Size of Culvert 36 inch
Type Culvert Metal

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 3 SERIOUS
Conduit Alignment 8 VERY GOOD
Shape 6 SATISFACTORY
Seams and Joints 7 GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail 3 Serious Misalignment of more than 6 posts in a row with serious settlement and rotation.
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.
Comments Layers of flaking rust on invert with perforations
Owner Rapp, Aaron
Completed DateTime 01/24/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage
Request Status 5 - Closed