

Title * Ware PIK-118-0.85
Culvert/Bridge Number PIK-118-0.85
Geo Location 40.054587785125044 -83.50541704402053
General Appraisal 8 Very good condition - no problems noted
Span Size 53inches
Culvert Length 32 ft
Size of Culvert 34x53
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 7 GOOD
Conduit Alignment 8 VERY GOOD
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 6 Satisfactory Conduit waterway blockage is less than 10% of the cross-sectional area of the opening. Sediment buildup causing flow through 1 of 2 pipes.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 6 Satisfactory Minor pavement deterioration: Minor potholes and cracking. Minor settlement.
Guardrail
Embankment
Comments Concrete edge is cracked and chipped on inlet of culvert. Tile breather on outlet side needs a grate or lid. Edge of pavement deteriorated on inlet side of culvert
Owner Rapp, Aaron
Completed DateTime 11/18/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage