

**Title \*** William-Lucas STO-89-1.40  
**Culvert/Bridge Number** STO-89-1.40  
**Geo Location** 39.755365387615306 -83.63840103149415  
**General Appraisal** 9 As built condition  
**Span Size** 30 inch  
**Culvert Length** 32 feet  
**Size of Culvert** 19x30  
**Type Culvert** RCP

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.  
**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.  
**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.  
**Guardrail**  
**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.  
**Comments**  
**Owner** Rapp, Aaron  
**Completed DateTime** 01/28/2025 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage  
**Request Status** 5 - Closed