

**Title \*** Amish Pike CAN-30A-0.20

**Culvert/Bridge Number** CAN-30A-0.20

**Geo Location** 40.05600006426482 -83.34476754069328

**General Appraisal** 6 Satisfactory condition - structural elements show some deterioration

**Span Size** 85 inches

**Culvert Length** 40 ft

**Size of Culvert** 85x54 Steel Arch

**Type Culvert** Metal

### Conduit

**Level of Inspection** M- MANNED ENTRY INSPECTION

**Material** 6 SATISFACTORY

**Conduit Alignment** 8 VERY GOOD

**Shape** 8 VERY GOOD

**Seams and Joints** 7 GOOD

**Slab**

**Abutments**

**Headwalls**

**End Structure**

### Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.

**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 8 Very Good Hairline cracks in pavement. Minor scaling.

**Guardrail**

**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

**Comments** Heavy layers of rust throughout invert.

**Owner** Rapp, Aaron

**Completed DateTime** 12/05/2024 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage