

Title * Becker SOM-120-0.53
Culvert/Bridge Number SOM-120-0.53
Geo Location 40.03048595257815 -83.46636512368546
General Appraisal 8 Very good condition - no problems noted
Span Size 82 inches
Culvert Length 32 ft
Size of Culvert 82x53 arch
Type Culvert Metal

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 8 VERY GOOD
Conduit Alignment 9 EXCELLENT
Shape 8 VERY GOOD
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Slight flaking rust on invert
Owner Rapp, Aaron
Completed DateTime 11/20/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage