

Title * Bragg RAN-68-1.17
Culvert/Bridge Number RAN-68-1.17
Geo Location 39.715172876503715 -83.33699315786363
General Appraisal 5 Fair condition - all primary structural elements are sound, but may have minor section loss
Span Size 36 inch
Culvert Length 40 feet
Size of Culvert 36 inch
Type Culvert Cast Iron

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 5 FAIR
Conduit Alignment 5 FAIR
Shape 7 GOOD
Seams and Joints 5 FAIR
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.
Comments
Owner Crews, Mark
Completed DateTime 01/16/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage