

Title * Cemetery Pike DAR-34-0.41
Culvert/Bridge Number DAR-34-0.41
Geo Location 40.09349404287583 -83.25019687414171
General Appraisal 9 As built condition
Span Size 30inches
Culvert Length 80ft
Size of Culvert 30 inch
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 8 VERY GOOD
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail 9 Excellent Guardrail is free from deficiencies.
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Update in inventory
Owner Rapp, Aaron
Completed DateTime 12/06/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage