

Title * Counts RAN-75-0.08

Culvert/Bridge Number RAN-75-0.08

Geo Location 39.71322257450048 -83.46432365477087

General Appraisal 5 Fair condition - all primary structural elements are sound, but may have minor section loss

Span Size

Culvert Length

Size of Culvert

Type Culvert Metal

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

Material 5 FAIR

Conduit Alignment 8 VERY GOOD

Shape 7 GOOD

Seams and Joints 7 GOOD

Slab

Abutments

Headwalls

End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.

Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.

Guardrail 9 Excellent Guardrail is free from deficiencies.

Embankment 8 Very Good Minor rutting from drainage; vegetation intact.

Comments Layers of rust

Owner Rapp, Aaron

Completed DateTime 01/23/2025 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage