

**Title \*** Dorn RAN-76-0.38  
**Culvert/Bridge Number** RAN-76-0.38  
**Geo Location** 39.72228654956034 -83.44462886452678  
**General Appraisal** 8 Very good condition - no problems noted  
**Span Size** 8 feet  
**Culvert Length** 32 feet  
**Size of Culvert** 4x8 box  
**Type Culvert** Concrete

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 8 VERY GOOD

### Slab

### Abutments

**Headwalls** 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.  
**Scour** 9 Excellent No evidence of scour at either inlet or outlet of conduit.  
**Channel Projection** 9 Excellent Embankment protection not required or in stable condition.

### Approaches

**Pavement** 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.  
**Guardrail**

**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

### Comments

**Owner** Rapp, Aaron

**Completed DateTime** 01/23/2025 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage