

**Title \*** Dyer PLE-66-2.30  
**Culvert/Bridge Number**  
**Geo Location** 39.74455123318796 -83.3293864130974  
**General Appraisal** 8 Very good condition - no problems noted  
**Span Size** 42 inch  
**Culvert Length** 60 feet  
**Size of Culvert** 42 inch  
**Type Culvert** RCP

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 6 Satisfactory Conduit waterway blockage is less than 10% of the cross-sectional area of the opening. Sediment buildup causing flow through 1 of 2 pipes.  
**Scour** 9 Excellent No evidence of scour at either inlet or outlet of conduit.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 8 Very Good Hairline cracks in pavement. Minor scaling.  
**Guardrail** 6 Satisfactory Noticeable sag and misalignment in the guardrail that may indicate possible settlement; minor rotation of posts; up to 3 posts in a row affected.  
**Embankment** 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.  
**Comments**  
**Owner** Rapp, Aaron  
**Completed DateTime** 01/17/2025 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage