

Title * Finley-Guy MON-123-6.07

Culvert/Bridge Number

Geo Location 40.04138828644215 -83.37005138397218

General Appraisal 8 Very good condition - no problems noted

Span Size 8 ft

Culvert Length 40 ft

Size of Culvert 8x4 Box

Type Culvert Concrete

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

Material 9 EXCELLENT

Conduit Alignment 9 EXCELLENT

Shape 9 EXCELLENT

Seams and Joints 8 VERY GOOD

Slab

Abutments

Headwalls 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less

End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.

Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.

Guardrail 9 Excellent Guardrail is free from deficiencies.

Embankment 8 Very Good Minor rutting from drainage; vegetation intact.

Comments Possible movement to head wall on top of box.

Owner Rapp, Aaron

Completed DateTime 12/04/2024 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage