

Title * Foster-Redman RAN-74-1.56
Culvert/Bridge Number RAN-74-1.56
Geo Location 39.754617896279655 -83.41379553079607
General Appraisal 7 Good condition - some minor problems
Span Size 65 inches
Culvert Length 41 feet
Size of Culvert 48x65 steel arch
Type Culvert Metal

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 7 GOOD
Conduit Alignment 8 VERY GOOD
Shape 7 GOOD
Seams and Joints 7 GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.
Comments
Owner Rapp, Aaron
Completed DateTime 01/23/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage