

**Title \*** Glade Run UNI-70-1.96  
**Culvert/Bridge Number** UNI-70-1.96  
**Geo Location** 39.874437507755836 -83.3493956923485  
**General Appraisal** 7 Good condition - some minor problems  
**Span Size** 96 inches  
**Culvert Length** 40 feet  
**Size of Culvert** 96x69 Steel Arch  
**Type Culvert** Metal

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 7 GOOD  
**Conduit Alignment** 8 VERY GOOD  
**Shape** 8 VERY GOOD  
**Seams and Joints** 8 VERY GOOD  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.  
**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 8 Very Good Hairline cracks in pavement. Minor scaling.  
**Guardrail** 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.  
**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.  
**Comments**  
**Owner** Rapp, Aaron  
**Completed DateTime** 01/03/2025 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage