

Title * Green Lane SOM-112-3.00
Culvert/Bridge Number SOM-112-3.00
Geo Location 39.99219718167802 -83.46152044256387
General Appraisal 8 Very good condition - no problems noted
Span Size 5 ft
Culvert Length 48 ft
Size of Culvert 60 inch
Type Culvert RCP

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 8 VERY GOOD
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment
Comments Conseal between joints has fallen through joint allowing water to infiltrate through top of culvert
Owner Rapp, Aaron
Completed DateTime 11/22/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage