

Title * Green Lane SOM-112-3.04
Culvert/Bridge Number SOM-112-3.04
Geo Location 39.99549314056161 -83.46759913725569
General Appraisal 9 As built condition
Span Size 5ft
Culvert Length 80 ft
Size of Culvert 60 inch
Type Culvert Plastic

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments
Owner Rapp, Aaron
Completed DateTime 11/22/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage