Title *Hicks PLE-67-0.38Culvert/Bridge NumberPLE-67-0.38Geo Location39.7017027527569 -83.30565690994264General Appraisal9 As built conditionSpan Size30 inchCulvert Length32 feetSize of Culvert30 inchType CulvertRCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY) Material 9 EXCELLENT Conduit Alignment 9 EXCELLENT Shape 9 EXCELLENT Seams and Joints 9 EXCELLENT Slab Abutments Headwalls End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.

Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.

Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.

Guardrail

Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Crews, Mark

Completed DateTime 01/16/2025 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage