

Title * Hicks PLE-67-0.82
Culvert/Bridge Number
Geo Location 39.70785507643485 -83.30871518609075
General Appraisal 7 Good condition - some minor problems
Span Size 30 inch
Culvert Length 40 feet
Size of Culvert 30 inch
Type Culvert Plastic

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 7 GOOD
Conduit Alignment 7 GOOD
Shape 7 GOOD
Seams and Joints 7 GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 6 Satisfactory lows through 1 of 2 pipes in multi-cell. Flows along or into one abutment or wingwall or headwall. Doesn't flow through center of the conduit
Conduit Waterway Blockage 2 Critical Conduit waterway blockage is 80% or greater of the cross-sectional area of the opening. Frequent overtopping of roadway with significant traffic delays.
Scour 3 Serious Major scour holes, 3 feet or deeper, at inlet or outlet undermining cutoff walls or headwalls. Footing is undermined.
Channel Projection 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments Culvert completely full of water. Could not inspect. Could not find buried inlet. Water backs up at inlet.
Owner Crews, Mark
Completed DateTime 01/16/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage