

**Title \*** Kiousville-Georgesville FAI-53-3.79

**Culvert/Bridge Number** FAI-53-3.79

**Geo Location** 39.844117858671936 -83.25934723019601

**General Appraisal** 6 Satisfactory condition - structural elements show some deterioration

**Span Size** 115 inches

**Culvert Length** 40 feet

**Size of Culvert** 115x70 Steel Arch

**Type Culvert** Metal

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

**Material** 6 SATISFACTORY

**Conduit Alignment** 8 VERY GOOD

**Shape** 8 VERY GOOD

**Seams and Joints** 8 VERY GOOD

**Slab**

**Abutments**

**Headwalls**

**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

**Conduit Waterway Blockage** 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.

**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.

**Guardrail**

**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

**Comments** Standing water in invert, but can see light layer of rust on invert.

**Owner** Rapp, Aaron

**Completed DateTime** 01/03/2025 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage