

Title * Little Darby MON-116-0.61
Culvert/Bridge Number MON-116-0.61
Geo Location 39.982951989265096 -83.37435230612755
General Appraisal 8 Very good condition - no problems noted
Span Size 78inch
Culvert Length 48ft
Size of Culvert 78 inch
Type Culvert Plastic

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 8 VERY GOOD
Conduit Alignment 8 VERY GOOD
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.
Guardrail 6 Satisfactory Noticeable sag and misalignment in the guardrail that may indicate possible settlement; minor rotation of posts; up to 3 posts in a row affected.
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.
Comments
Owner Rapp, Aaron
Completed DateTime 11/26/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage