Title * McClimansville Cemetery PLE-57-1.10A

Culvert/Bridge Number PLE-57-1.10A

Geo Location 39.73482653102515 -83.25062334537508

General Appraisal 8 Very good condition - no problems noted

Span Size 8 feet

Culvert Length 40 feetSize of Culvert 8x4 boxType Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION

Material 8 VERY GOOD

Conduit Alignment 9 EXCELLENT

Shape 9 EXCELLENT

Seams and Joints 7 GOOD

Slab

Abutments

Headwalls 9 Excellent No signs of distress, no discoloration.

End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.

Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.

Guardrail 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.

Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Rapp, Aaron

Completed DateTime 01/16/2025 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage