

Title * Mechanicsburg-Sanford PIK-27-1.40
Culvert/Bridge Number PIK-27-1.40
Geo Location 40.05050596468052 -83.49075831639476
General Appraisal 8 Very good condition - no problems noted
Span Size 30inches
Culvert Length 40 ft
Size of Culvert 30 inch
Type Culvert Plastic

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 8 VERY GOOD
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Damage to top of bell on inlet
Owner Rapp, Aaron
Completed DateTime 11/20/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage