

Title * Middle Pike JEF-10-2.55
Culvert/Bridge Number JEF-10-2.55
Geo Location 39.98260979690672 -83.28007265925409
General Appraisal 8 Very good condition - no problems noted
Span Size 5 ft
Culvert Length 36 ft
Size of Culvert 5x2 box
Type Culvert Concrete

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 7 GOOD
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 7 Good Silt and gravel buildup restrict half of the channel. Tree or bush growing in the channel.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments
Owner Rapp, Aaron
Completed DateTime 12/18/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage