

Title * Morgan JEF-46-1.07
Culvert/Bridge Number JEF-46-1.07
Geo Location 39.996718415082135 -83.26691307127476
General Appraisal 8 Very good condition - no problems noted
Span Size 36 inch
Culvert Length 40ft
Size of Culvert 36 inch
Type Culvert Concrete

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 6 Satisfactory Riprap starting to wash away. Minor erosion. Cracked concrete channel protection at inlet of a conduit.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Erosion at inlet
Owner Rapp, Aaron
Completed DateTime 12/12/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage