**Title \*** Old Springfield UNI-13-0.93

**Culvert/Bridge Number** UNI-13-0.93

**Geo Location** 39.89883420733935 -83.53063121438028

**General Appraisal** 9 As built condition

**Span Size** 68 inch

**Culvert Length** 40 feet **Size of Culvert** 43x68

**Type Culvert** RCP

## Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

**Material** 9 EXCELLENT

**Conduit Alignment** 9 EXCELLENT

**Shape** 9 EXCELLENT

**Seams and Joints** 9 EXCELLENT

Slab

**Abutments** 

Headwalls

**End Structure** 

## Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.

**Scour** 9 Excellent No evidence of scour at either inlet or outlet of conduit.

**Channel Projection** 

## **Approaches**

**Pavement** 9 Excellent No noticeable defects.

Guardrail

**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

**Comments** 

Owner Rapp, Aaron

**Completed DateTime** 01/30/2025 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage

**Request Status** 5 - Closed