

Title * Plain City -Georgesville CAN-7-4.63
Culvert/Bridge Number
Geo Location 40.020838416433826 -83.26189398765565
General Appraisal 7 Good condition - some minor problems
Span Size 36 inch
Culvert Length 40 ft
Size of Culvert 36 inch
Type Culvert Cast Iron

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 7 GOOD
Conduit Alignment 7 GOOD
Shape 7 GOOD
Seams and Joints 7 GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail 9 Excellent Guardrail is free from deficiencies.
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Cast iron culvert under pavement. Plastic extensions. Joints are sealed with foam, must monitor.
Owner Rapp, Aaron
Completed DateTime 12/11/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage