

Title * Plain City-Georgesville CAN-7-5.15
Culvert/Bridge Number CAN-7-5.15
Geo Location 40.028368199988 -83.26186448335649
General Appraisal 7 Good condition - some minor problems
Span Size 8 ft
Culvert Length 48 ft
Size of Culvert 8x6 box
Type Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 7 GOOD
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab

Abutments

Headwalls 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.

Comments

Owner Rapp, Aaron
Completed DateTime 12/11/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage