

Title * Prairie RAN-77-0.07
Culvert/Bridge Number RAN-77-0.07
Geo Location 39.70923256245501 -83.50270673632623
General Appraisal 9 As built condition
Span Size 68 inches
Culvert Length 36 feet
Size of Culvert 43x68
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.
Comments Subsurface tile breather needs grate
Owner Rapp, Aaron
Completed DateTime 01/27/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage
Request Status 5 - Closed