

Title * Price-Hilliards CAN-32-.34
Culvert/Bridge Number CAN-32-.34
Geo Location 40.044589906661564 -83.34705956391915
General Appraisal 8 Very good condition - no problems noted
Span Size 36 inch
Culvert Length 56 ft
Size of Culvert 36 inch
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 7 Good Silt and gravel buildup restrict half of the channel. Tree or bush growing in the channel.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.
Guardrail 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments Silt build up in invert. Bank on outlet has started to settle and erode. Needs rip-rap. Blowouts to subsurface tile in bottom of ditch on inlet.
Owner Rapp, Aaron
Completed DateTime 12/02/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage