

**Title \*** Price-Hilliards CAN-32-1.30  
**Culvert/Bridge Number** CAN-32-1.30  
**Geo Location** 40.044830800673516 -83.3290457725525  
**General Appraisal** 7 Good condition - some minor problems  
**Span Size** 6ft  
**Culvert Length** 24 ft  
**Size of Culvert** 6x3 box  
**Type Culvert** Concrete

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 7 GOOD  
**Conduit Alignment** 8 VERY GOOD  
**Shape** 7 GOOD  
**Seams and Joints** 7 GOOD  
**Slab** 7 Good Hairline cracking with no single crack greater than  $\frac{1}{16}$  inch parallel to the direction of traffic. Light scaling less than  $\frac{1}{8}$  inch deep on less than 10% of exposed area.  
**Abutments** 7 GOOD  
**Headwalls** 7 Good Hairline cracking. No single crack greater than  $\frac{1}{16}$  inch. No rust staining. Minor rotation of less than 1 inch per foot.  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.  
**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 8 Very Good Hairline cracks in pavement. Minor scaling.  
**Guardrail** 6 Satisfactory Noticeable sag and misalignment in the guardrail that may indicate possible settlement; minor rotation of posts; up to 3 posts in a row affected.  
**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.  
**Comments** Delamination starting in various spots  
**Owner** Rapp, Aaron  
**Completed DateTime** 12/02/2024 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage