

Title * Rosedale-Milford Center MON-11-1.50
Culvert/Bridge Number MON-11-1.50
Geo Location 40.019882242883945 -83.43241676688196
General Appraisal 9 As built condition
Span Size 8 ft
Culvert Length 48 ft
Size of Culvert 8x4 box
Type Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments
Owner Rapp, Aaron
Completed DateTime 11/25/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage