

Title * Rosedale-Milford Center MON-11-2.32
Culvert/Bridge Number MON-11-2.32
Geo Location 40.029637402752584 -83.43727724833873
General Appraisal 4 Poor condition - advanced section loss, deterioration, or spalling
Span Size 30 inches
Culvert Length 45 ft
Size of Culvert 30 inch
Type Culvert Plastic

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 7 GOOD
Conduit Alignment 6 SATISFACTORY
Shape 5 FAIR
Seams and Joints 4 POOR
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 6 Satisfactory Minor scour holes, 1 foot or less deep, developing at inlet or outlet. Footings along the side are exposed less than 6 inches.
Channel Projection 6 Satisfactory Riprap starting to wash away. Minor erosion. Cracked concrete channel protection at inlet of a conduit.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.
Guardrail
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments Culvert has egg-shaped. Joints are separating.
Owner Rapp, Aaron
Completed DateTime 11/25/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage