

Title * Rosedale Milford Center PIK-11-5.44
Culvert/Bridge Number PIK-11-5.44
Geo Location 40.074450903613695 -83.45070226597524
General Appraisal 9 As built condition
Span Size 6 ft
Culvert Length 32 ft
Size of Culvert 6x3 Box
Type Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour

Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment
Comments
Owner Rapp, Aaron
Completed DateTime
Request Category Culvert Inspection
Group Ops-Drainage