

**Title \*** Rosedale Milford Center PIK-11-6.01  
**Culvert/Bridge Number** PIK-11-6.01  
**Geo Location** 40.08035497212238 -83.45720288153343  
**General Appraisal** 9 As built condition  
**Span Size** 60 inches  
**Culvert Length** 40 ft  
**Size of Culvert** 60x38  
**Type Culvert** RCP

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.  
**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.  
**Scour**  
**Channel Projection**

### Approaches

**Pavement** 9 Excellent No noticeable defects.  
**Guardrail**  
**Embankment**  
**Comments**  
**Owner** Rapp, Aaron  
**Completed DateTime**  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage