

Title * Rosedale Milford Center PIK-11-6.78
Culvert/Bridge Number PIK-11-6.78
Geo Location 40.09050458809861 -83.46400719290074
General Appraisal 9 As built condition
Span Size 5 ft
Culvert Length 40 ft
Size of Culvert 60x38
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment
Comments Outlet side bank beginning to slump. May need rip-rap
Owner Rapp, Aaron
Completed DateTime 11/18/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage