

Title * Rosedale Milford Center PIK-11-7.30

Culvert/Bridge Number PIK-11-7.30

Geo Location 40.097361583210485 -83.46806341574076

General Appraisal 6 Satisfactory condition - structural elements show some deterioration

Span Size 92 inches

Culvert Length 40 ft

Size of Culvert 92x58

Type Culvert Metal

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION

Material 6 SATISFACTORY

Conduit Alignment 9 EXCELLENT

Shape 7 GOOD

Seams and Joints 7 GOOD

Slab

Abutments

Headwalls

End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.

Scour

Channel Projection 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

Approaches

Pavement 9 Excellent No noticeable defects.

Guardrail

Embankment

Comments Layers of rust on invert. No holes yet

Owner Rapp, Aaron

Completed DateTime 11/18/2024 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage