Title \*Rosedale PIK-25-1.79Culvert/Bridge NumberPIK-25-1.79Geo Location40.06893925646615 -83.47570235707185General Appraisal9 As built conditionSpan Size3ftCulvert Length56ftSize of Culvert36inType CulvertRCP

## Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY) Material 9 EXCELLENT Conduit Alignment 9 EXCELLENT Shape 9 EXCELLENT Seams and Joints 9 EXCELLENT Slab Abutments Headwalls End Structure

## Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.

**Scour** 9 Excellent No evidence of scour at either inlet or outlet of conduit.

**Channel Projection** 9 Excellent Embankment protection not required or in stable condition.

## Approaches

Pavement9 Excellent No noticeable defects.GuardrailEmbankmentCommentsOwnerRapp, AaronCompleted DateTime11/18/2024 12:00:00 AMRequest CategoryCulvert InspectionGroupOps-Drainage