Title \* Taylor-Blair JEF-14-3.60Culvert/Bridge NumberJEF-14-3.60Geo Location39.97710571078073 -83.31955209374429General Appraisal9 As built conditionSpan Size8ftCulvert Length40ftSize of Culvert8x5 boxType CulvertConcrete

## Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY) Material 9 EXCELLENT Conduit Alignment 9 EXCELLENT Shape 9 EXCELLENT Seams and Joints 9 EXCELLENT Slab Abutments Headwalls 9 Excellent No signs of distress, no discoloration. End Structure

## Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.

**Scour** 9 Excellent No evidence of scour at either inlet or outlet of conduit.

**Channel Projection** 9 Excellent Embankment protection not required or in stable condition.

## Approaches

**Pavement**7 Good Minor problems: Raveling, hairline or map cracking. No settlement.**Guardrail** 

**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Rapp, Aaron

**Completed DateTime** 12/18/2024 12:00:00 AM

**Request Category** Culvert Inspection

Group Ops-Drainage