

Title * Thomas MON-121-1.09
Culvert/Bridge Number MON-121-1.09
Geo Location 40.03153440203317 -83.45754029417301
General Appraisal 9 As built condition
Span Size 8 ft
Culvert Length 32 ft
Size of Culvert 8x6 box
Type Culvert Concrete

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment
Comments
Owner Rapp, Aaron
Completed DateTime 11/20/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage