

Title * Val Wilson SOM-108-0.40
Culvert/Bridge Number SOM-108-0.40
Geo Location 39.95177359679997 -83.52297082543375
General Appraisal 7 Good condition - some minor problems
Span Size 30 inch
Culvert Length 40 feet
Size of Culvert 19x30
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 8 VERY GOOD
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 6 Satisfactory Minor erosion caused by drainage.
Comments Depression in berm over culvert. Could be caused by subsurface tile.
Owner Rapp, Aaron
Completed DateTime 01/30/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage
Request Status 5 - Closed