

Title * Woods-Opossum PLE-56-2.13
Culvert/Bridge Number PLE-56-2.13
Geo Location 39.766392261948326 -83.24990317225456
General Appraisal 8 Very good condition - no problems noted
Span Size 60 inch
Culvert Length 40 feet
Size of Culvert 38x60
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments
Owner Rapp, Aaron
Completed DateTime 01/15/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage