

Van Wagener Road No. 1
MADISON CO. ROAD RECORD

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township OAK RUN

No. 84 - C

Sec. _____

Shipping Point _____

Class of Traffic _____

Distance _____

Built by _____

Date _____

Price \$ _____

Surveyed by _____

BRICK	CONCRETE	SLAG—LIMESTONE	GRAVEL	
Kind of foundation _____	Thickness _____	Bottom { <div style="display: inline-block; vertical-align: top; margin-right: 5px;"> Filler _____ Thickness _____ Binder _____ Size _____ </div> <div style="display: inline-block; vertical-align: top;"> Center _____ Edge _____ </div>	Thickness _____	
Thickness of foundation _____	Kind of Cement _____		Top Course { <div style="display: inline-block; vertical-align: top; margin-right: 5px;"> Thickness _____ Filler _____ Size _____ Binder _____ </div> <div style="display: inline-block; vertical-align: top;"> Center _____ Edge _____ </div>	Width _____
Make of brick _____	Mixture _____			Crown _____
Width _____	Material { Gravel _____ Slag _____ Stone _____	Binder, Method _____		Cu. yds. Mat. _____
Crown _____	Width _____	Width _____		
Cushion _____	Crown _____	Crown _____		
Filler _____	Kind of expansion joints } _____	Cu. yds. Mat. _____		
Kind of curb _____				
Size of curb _____ X				
<input type="checkbox"/> yds brick	Cu. yds. concrete _____			
Cu. yds of base _____				

GENERAL

Total length 2.03 miles.

Distance C. to C. Ditch _____

No. of stone culverts _____

No. of C. I. P. _____

Depth of Ditches _____

Distance berm to berm _____

No. of steel bridges _____

No. concrete culverts _____

No. of cor. pipe _____

Has location been changed _____

Width of R. W. 48'

No. Con. bridges _____

No. of wood bridges _____

Total excavation _____

Location on R. W. _____

INSPECTION OF IMPROVED ROADS.

Date of Inspection		1-20			
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG-LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL				19.	
Condition of ditches					
Condition of berms					

Van Wagener No. 2 Road
MADISON CO. ROAD RECORD

THE COLUMBUS BANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township OAK RUN RANGE No. 85-C

Sec.

Class of Traffic

Shipping Point

Distance

Built by Date Price \$

Surveyed by

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation <u> </u>	Thickness <u> </u>	Bottom { Filler <u> </u> Center <u> </u> Thickness <u> </u> Edge <u> </u> Binder <u> </u> Size <u> </u>	Thickness <u> </u>
Thickness of foundation <u> </u>	Kind of Cement <u> </u>		Width <u> </u>
Make of brick <u> </u>	Mixture <u> </u>	Top Course { Thickness <u> </u> Center <u> </u> Filler <u> </u> Edge <u> </u> Size <u> </u> Binder <u> </u>	Crown <u> </u>
Width <u> </u>	Material { Gravel <u> </u> Slag <u> </u> Stone <u> </u>		Cu. yds. Mat. <u> </u>
Crown <u> </u>	Width <u> </u>	Binder, Method <u> </u>	
Cushion <u> </u>	Crown <u> </u>	Width <u> </u>	
Filler <u> </u>	Kind of expansion joints } <u> </u>	Crown <u> </u>	
Kind of curb <u> </u>		Cu. yds. concrete <u> </u>	Cu. yds. Mat. <u> </u>
Size of curb <u> </u> X <u> </u>			
<input type="checkbox"/> yds brick <u> </u>			
Cu. yds of base <u> </u>			

GENERAL

Total length 1.87 miles.
 Distance C. to C. Ditch
 No. of stone culverts
 No. of C. I. P.
 Depth of Ditches

Distance berm to berm
 No. of steel bridges
 No. concrete culverts
 No. of cor. pipe
 Has location been changed

Width of R. W. 40'
 No. Con. bridges
 No. of wood bridges
 Total excavation
 Location on R. W.

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLABS—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					