Cemetery Pike DAR-34-1.61 Title * Culvert/Bridge Number DAR-34-1.61 40.10366545417419 -83.23082730174066 Geo Location **General Appraisal** 9 As built condition Span Size 48 inch **Culvert Length** 40ft Size of Culvert 48 inch Type Culvert RCP

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION Material 9 EXCELLENT Conduit Alignment 9 EXCELLENT Shape 9 EXCELLENT Seams and Joints 8 VERY GOOD Slab Abutments Headwalls End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.

Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.

Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.

Guardrail

Embankment 8 Very Good Minor rutting from drainage; vegetation intact.

Comments

Owner Rapp, Aaron

Completed DateTime 12/06/2024 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage