Title * lams DAR-35-1.10 Culvert/Bridge Number DAR-35-1.10 40.08909365417005 -83.22396352887154 Geo Location General Appraisal 9 As built condition Span Size 8ft Culvert Length 40ft Size of Culvert 8x4 box Type Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION Material 9 EXCELLENT Conduit Alignment 9 EXCELLENT Shape 9 EXCELLENT Seams and Joints 9 EXCELLENT Slab Abutments Headwalls 9 Excellent No signs of distress, no discoloration. End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.

Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.

Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.

Guardrail

Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Rapp, Aaron

Completed DateTime 12/06/2024 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage