

Title * Tradersville-Brighton SOM-113-3.92
Culvert/Bridge Number SOM-113-3.92
Geo Location 40.01731762529549 -83.46580299371863
General Appraisal 8 Very good condition - no problems noted
Span Size 8ft
Culvert Length 32ft
Size of Culvert 8x4 box
Type Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 8 VERY GOOD
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls 9 Excellent No signs of distress, no discoloration.
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Slightly chipped corners on sections of box. One spot has exposed rebar.
Owner Rapp, Aaron
Completed DateTime 11/22/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage