

Slaughter Road MADISON CO. ROAD RECORD

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

Township STOKES

No. 79-6

Sec. _____

79-5406

Shipping Point _____

Class of Traffic MEDIUM

Distance _____

Built by _____

Date 1870

Price \$ 4750⁰⁰

Surveyed by J. Arnett

BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler..... Thickness } Center..... Binder..... Size.....	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____		Width <u>15'</u>
Make of brick _____	Mixture _____		Crown <u>8"</u>
Width _____	Material { Gravel..... Slag..... Stone.....		Cu. yds. Mat. <u>2933¹ 1/2 mi.</u>
Crown _____	Width _____	Top Course { Thickness } Center..... Filler..... Size..... Binder.....	
Cushion _____	Crown _____		
Filler _____	Kind of expansion joints } _____		
Kind of curb _____	Cu. yds. concrete _____		
Size of curb <u>X</u>		Binder, Method _____	
<input type="checkbox"/> yds brick _____		Width _____	
Cu. yds of base _____		Crown _____	
		Cu. yds. Mat. _____	

GENERAL

Total length 1.79 miles.
Distance C. to C. Ditch _____
No. of stone culverts _____
No. of C. I. P. _____
Depth of Ditches 2 1/2 (min)

Distance berm to berm 26'
No. of steel bridges _____
No. concrete culverts _____
No. of cor. pipe _____
Has location been changed No.

Width of R. W. 50'
No. Con. bridges _____
No. of wood bridges _____
Total excavation _____
Location on R. W. Center

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					