

IMPROVED

Bonner Road
MADISON CO. ROAD RECORD

THE COLUMBUS BLANK BOOK MFG. CO., COL., O. 5908

Township PAINT, UNIONNo. 145-T

Sec. _____

Shipping Point _____

Class of Traffic _____

Distance _____

Built by _____

Date _____

Price \$ _____

Surveyed by _____

BRICK

CONCRETE

SLAG-LIMESTONE

GRAVEL

Kind of foundation _____	Thickness _____	Bottom { Filler _____ Thickness { Center _____ Edge _____ Binder _____ Size _____	Thickness _____
Thickness of foundation _____	Kind of Cement _____		Width _____
Make of brick _____	Mixture _____	Top Course { Thickness { Center _____ Edge _____ Filler _____ Size _____ Binder _____	Crown _____
Width _____	Material { Gravel _____ Slag _____ Stone _____		Cu. yds. Mat. _____
Crown _____	Width _____	Binder, Method _____	
Cushion _____	Crown _____	Width _____	
Filler _____	Kind of expansion joints } _____	Crown _____	
Kind of curb _____		Cu. yds. concrete _____	Cu. yds. Mat. _____
Size of curb _____ X _____			
[] yds brick _____			
Cu. yds of base _____			

GENERAL

Total length 1.80 miles.
 Distance C. to C. Ditch _____
 No. of stone culverts _____
 No. of C. I. P. _____
 Depth of Ditches _____

Distance berm to berm _____
 No. of steel bridges _____
 No. concrete culverts _____
 No. of cor. pipe _____
 Has location been changed _____

Width of R. W. 33'
 No. Con. bridges _____
 No. of wood bridges _____
 Total excavation _____
 Location on R. W. _____

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					