

Drury Road

THE LUMBUS BLANK BOOK MFG. CO., COL., O. 5908

IMPROVED

MADISON CO. ROAD RECORD

Township PAINT

No. 23-C

Sec. _____

Shipping Point _____

Class of Traffic HEAVY

Distance _____

Built by _____

Date 1906

Price \$ 1115.00⁰⁰

Surveyed by H. L. McCafferty

BRICK

CONCRETE

SLAG-LIMESTONE

GRAVEL

Kind of foundation _____
Thickness of foundation _____
Make of brick _____
Width _____
Crown _____
Cushion _____
Filler _____
Kind of curb _____
Size of curb X _____
☐ yds brick _____
Cu. yds of base _____

Thickness _____
Kind of Cement _____
Mixture _____
Material ☐ Gravel _____
☐ Slak _____
☐ Stone _____
Width _____
Crown _____
Kind of expansion joints ☐ _____
Cu. yds. concrete _____

Bottom ☐ Filler _____
☐ Thickness Center _____
☐ Binder Edge _____
☐ Size _____
Top Course ☐ Thickness Center _____
☐ Filler Edge _____
☐ Size _____
☐ Binder _____
Binder, Method _____
Width _____
Crown _____
Cu. yds. Mat. _____

Thickness 12"
Width 10'
Crown 6"
Cu. yds. Mat. _____

GENERAL

Total length 3.72 miles.
Distance C. to C. Ditch _____
No. of stone culverts _____
No. of C. I. P. _____
Depth of Ditches 1 1/2 min

Distance berm to berm 26'
No. of steel bridges _____
No. concrete culverts _____
No. of cor. pipe _____
Has location been changed No

Width of R. W. 30'
No. Con. bridges _____
No. of wood bridges _____
Total excavation _____
Location on R. W. 4th of 4

INSPECTION OF IMPROVED ROADS.

Date of Inspection_____					
BRICK					
Condition of brick_____					
Condition of filler_____					
Condition of curb_____					
CONCRETE					
Condition of concrete_____					
Condition of surface_____					
SLAG—LIMESTONE					
Condition of foundation_____					
Condition of top_____					
Does top need to be scarified					
Are there ruts in road_____					
GRAVEL					
Condition of surface_____					
Is road rutted_____					
GENERAL					
Condition of ditches_____					
Condition of berms_____					