IMPROVED	大いしょかり i MADISON CO. R		IS BLANK BOOK MFG. CO., COL., O. 5908				
Township CAMAAN_	No. 130 -	<u>C</u>	Sec				
	Shipping Point						
Class of Traffic	Distance						
Built by	Date		Price \$				
Surveyed by							
BRICK	CONCRETE	SLAG-LIMESTONE	GRAVEL				
Make of brick	Thickness Kind of Cement Mixture Material { Sinv Stone Width Crown Kind of expansion joints} Cu. yds. concrete	Top Course Filler	WidthCrown				
Total length \.Z.8 Distance C. to C. Ditch No. of stone culverts No. of C. I. P. Depth of Ditches	No. of steel br No. concrete No. of cor. pi	ridges N culverts N	Vidth of R. W. 45 No. Con. bridges No. of wood bridges Cotal excavation Cocation on R. W.				

INSPECTION OF IMPROVED ROADS.

Date of Inspection					<u> </u>
BRICK ,					
Condition of brick	· · · ·			•	-
Condition of filler					
Condition of curb					
CONCRETE	,				
Condition of concrete					
Condition of surface					
SLAG-LIMESTONE					
Condition of foundation	•	•			ļ <u></u>
Condition of top	<u> </u>	<u> </u>	<u> </u>	•	
Does top need to be scarified			<u> </u>	<u> </u>	
Are there ruts in road				<u> </u>	
GRAVEL	•				
Condition of surface				·	<u> </u>
Is road ruted	<u> </u>	<u> </u>			
GENERAL				٠.,	
Condition of ditches				<u> </u>	<u> </u>
Condition of berms	•				!
		<u>.</u>	<u> </u>		!
taid out 1892. See 18d. Rec. 70 page 3 Improved 1836 " 18d. Imp. Row 4 "	25 TE 25/			•	•